

5-3-05
12.38v.9

NOV 2004

Work Task: 25169 - 1

Monthly AST (Above-ground Storage Tank) Visual Inspection - Fluid Vessals



AGC2E000720

Description: Monthly AST (Above-ground Storage Tank) Visual Inspection

Visually inspect the outside of the container for (From SPCC Requirement [40 CFR 112.8(c)(6)]):

1. Signs of deterioration
2. Signs of Discharges
3. Signs of Accumulation of oil inside diked areas

Record finding in Work Order Close Out Comments.

Inspect all vessels on the attached list.

Work Type: 4. Environmental

Work order: 25169 Monthly AST (Above-ground Storage Tank) Visual Inspection



Entity to Work On

Number: 710

Name: Common Plant Services

Personnel

Planner: MacVeigh Craig

Supervisor: Parker Sid

Shutdown Information

Shut entity down while work is in progress? No

Seattle Plant

Printed by: Austell Carey

Printed on: 5/3/2005

Other Entities to Shut Down

| Number | Name |
|--------|------|
|--------|------|

Time Frame for Completing the Work

Priority: 3 Routine

Start no earlier than: 2004/10/30 09:27:24.00

Finish no later than: 2004/11/20 09:27:24.00

Shutdown period:

Estimated duration:

Planned duration: 4.00 hours

Job Premiums

Job type:

Shift:

Backlog Information:

Probability of Satisfaction: High

Material availability: Material not required

Estimated material availability date:

Seattle Plant

Printed by: Austell Carey

Printed on: 5/3/2005

Failure Information

Generate failure analysis information: No
Reason for failure: Closed
Root cause: Lubrication
Action taken: Closed
Equipment failed due to:
Entity:
Catalog item:

Requirements

| Part/Service | Quantity | Item Number | Probability of Satisfaction | Availability | Estimated Material Availability Date | Storeroom |
|--------------|----------|-------------|-----------------------------|--------------|--------------------------------------|-----------|
|--------------|----------|-------------|-----------------------------|--------------|--------------------------------------|-----------|

| Trade | Quantity | Time Required |
|----------------|----------|---------------|
| PM Lube Spec | 1.00 | 4.00 hours |
| PM Electrician | 0.00 | 0.00 hour |

Safety Instructions for this Work

Seattle Plant

Printed by: Austell Carey
Printed on: 5/3/2005

Work Task: Monthly AST (Above-ground Storage Tank) Visual Inspection - Fluid Vessals

AGC2E000723

Activities

| Activity Number | Activity | Record Statistics | Record Downtime | Component Movement | Calibration Instrument Used | Comments |
|--------------------------|---------------|----------------------|--------------------|-----------------------|--------------------------------|----------|
| <input type="checkbox"/> | | | | | | |
| Processed: | Processed on: | | Done by: | | | |

Seattle Plant

Printed by: Austell Carey
Printed on: 5/3/2005